

<p align="center"><b>Change Proposal – F40/01 (Page 1 of 2)</b></p>	<p><b>CP No: 850</b> <i>(mandatory by BSCCo)</i></p>
<p><b>Title</b> <i>(mandatory by originator)</i> Creation of exception log in SVAA software for timestamp errors in D0277 Flow.</p>	
<p><b>Description of Change</b> <i>(mandatory by originator)</i> There has been an instance of the Daily Profile Production (DPP) run failing because of a problem with the D0277 Teleswitch Contact Interval (TCI) Data File. This problem occurred as the times inputted by the Teleswitch Agent are rounded to the nearest minute at Electricity Association Services Limited (EASL). In this certain instance the rounding of these times resulted in the on/off times being the same, causing the loading of the data by the Supplier Volume Allocation Agent (SVAA) to fail. As this is recognised as a format error, rather than a validation error, an error log and not an exception report was generated, which failed to identify the source of the problem. It is proposed that the SVAA software is modified to include a check for duplicated TCI Effective Times as an extra validation check, so that such duplications would cause a validation error, resulting in an exception report being generated.</p>	
<p><b>Proposed Solution(s)</b> <i>(mandatory by originator)</i> An amendment is required to the SVAA User Requirement Specification (URS) to add a new validation check to clause 6.2.14.6 (process 2.2.6 – Load Teleswitch Contact Details), as follows:  <u>“iv) for each unique Teleswitch Date, Teleswitch User, Teleswitch Group and Teleswitch Contact combination in a UTC file there is no duplication of Teleswitch Contact Interval Effective Times. If there is, the data will be rejected.”</u>  Note that the D0277 File is referred to as the UTC file in the proposed text, which is consistent with the SVAA URS.</p>	
<p><b>Justification for Change</b> <i>(mandatory by originator)</i> The DPP run for Settlement date 16/02/2001 failed to load due to the times inputted by the Teleswitch Agent and the reason for this failure was unclear from the error report that was generated. Specifying an exact route cause ensures that the problem can be resolved more easily.</p>	
<p><b>Other Configurable Items Potentially Affected by Proposed Solution(s)</b> <i>(optional by BSCCo)</i> SVAA software SVAA/ISRA Documentation</p>	
<p><b>Impact on Core Industry Documents</b> <i>(optional by originator)</i></p>	

<p align="center"><b>Change Proposal – F40/01 (Page 2 of 2)</b></p>	<p><b>CP No:</b> <i>(mandatory by BSCCo)</i></p>
<p><b>Related Changes and/or Projects</b> <i>(mandatory by BSCCo)</i> None</p>	
<p><b>Originator's Details:</b></p> <p><b>BCA Name:</b> Tom Cash.....</p> <p><b>Organisation:</b> ELEXON</p> <p><b>Email Address:</b> .....</p> <p><b>Date:</b> 29/08/02.....</p> <p><b>Organisation:</b> .....</p>	
<p>Attachments: Y/N</p>	