Change Proposal – BSCP40/02	CP No: 1279 *Version No: 1.0* *(mandatory by BSCCo)*

Title *(mandatory by originator)*
Housekeeping Change to BSCP515 – Licensed Distribution

Description of Problem/Issue *(mandatory by originator)*
On page 11 of BSCP515, step 3.3.4 has the WHEN action of 'Within 5WD[1] of 3.3.2'. This should say 'Within 5WD of 3.3.3'. In addition footnote 4, also on page 11, refers to step 3.3.4. This should be 3.3.3.

We implemented CP1199 in February 2008; however, the agreed redlined text contained this error. CP1199 introduced several changes to the steps of 3.3, and moved step 3.3.2 to 3.3.3 but the reference in 3.3.4 was not updated. CP1199 also moved step 3.3.3 to 3.3.4, but didn't update the reference in footnote 4.

The current text implies that the LDSO[2] should send the D0215 (Provision of Site Technical Details) 5WDs after the SMRA[3] notifies them that a Supplier has been assigned to the new MSID[4] in SMRS. Instead of 5WDs after the MOA[5] sends the D0170 request (Request for Metering System Related Details). This implies that the LDSO may attempt to send a D0215 flow to the MOA, before the Supplier has appointed them.

Footnote 4 goes some way to clarify this, stating: 'Note that a Supplier must have appointed an MOA for that Metering System before step 3.3.4 can occur.' However, step 3.3.3, (where the MOA sends the D0170 to the LDSO), also cannot occur until the Supplier has appointed the MOA; so footnote 4 should refer to step 3.3.3.

Proposed Solution *(mandatory by originator)*
Update the WHEN action in step 3.3.4 to say 'Within 5WD of 3.3.3'.

Update footnote 4 to say: 'Note that a Supplier must have appointed an MOA for that Metering System before step 3.3.3 can occur.'

Justification for Change *(mandatory by originator)*
Two participants have highlighted to us that they find this section confusing and are unsure of their obligations. We believe that this minor housekeeping change will clarify the existing obligations, and prevent further confusion.

This change will correct a change that was clearly not intended by CP1199.

To which section of the Code does the CP relate, and does the CP facilitate the current provisions of the Code? *(mandatory by originator)*
Yes, this relates to Section K, 2.4.3.

[1] Working Days
[2] Licensed Distribution System Operator
[3] Supplier Meter Registration Agent
[4] Metering System Identifier
[5] Meter Operator Agent

Estimated Implementation Costs *(mandatory by BSCCo)* We will implement this CP at zero cost.
Configurable Items Affected by Proposed Solution(s) *(mandatory by originator)* BSCP515
Impact on Core Industry Documents or System Operator-Transmission Owner Code *(mandatory by originator)* None
Related Changes and/or Projects *(mandatory by BSCCo)* None
Requested Implementation Date ***(mandatory by originator)*** June 2009 **Reason:** Next available release
Version History ***(mandatory by BSCCo)*** This is Version 1.0 for approval
Originator's Details: ***BCA Name…Ysanne Hills*** ***Organisation…ELEXON*** ***Email Address…ysanne.hills@elexon.co.uk*** ***Telephone Number…0207 380 4162*** ***Date…04 February 2009***
Attachments: Yes *Attachment A – BSCP515 v8.1 redlined v0.1 (2 pages)*