

<b>Draft Change Proposal – BSCP40/01</b>	DCP No: 0029  <i>Version No: 1.0 (mandatory by BSCCo)</i>
<b>Title</b> <i>(mandatory by originator)</i> Recommendations of the Unmetered Supplies Expert Group	
<p><b>Description of Problem/Issue</b> <i>(mandatory by originator)</i></p> <p>As part of their 2006 report the Auditor identified a number of ‘Market Issues’ relating to Unmetered Supplies and the SVG agreed (SVG67/04) that a project and expert group (UMSEG) should be set up in order to address these Market Issues.</p> <p>The full recommendations of the UMSEG are contained in two documents:</p> <ul style="list-style-type: none"> <li>• The Solutions Document: <a href="http://www.elexon.co.uk/documents/BSC_Panel_and_Panel_Committees/SVG_Meeting_2007_-_079_-_Papers/SVG79_10a.pdf">http://www.elexon.co.uk/documents/BSC_Panel_and_Panel_Committees/SVG_Meeting_2007_-_079_-_Papers/SVG79_10a.pdf</a></li> <li>• The Walkthrough Report: <a href="http://www.elexon.co.uk/documents/BSC_Panel_and_Panel_Committees/SVG_Meeting_2007_-_079_-_Papers/SVG79_10b.pdf">http://www.elexon.co.uk/documents/BSC_Panel_and_Panel_Committees/SVG_Meeting_2007_-_079_-_Papers/SVG79_10b.pdf</a></li> </ul> <p>The Solution Document identifies specific issues arising directly from the Audit, while the Walkthrough Report details the results of a walkthrough initiated following the Auditor’s identification of inconsistencies between BSCP520 and BSCP504.</p> <p>At SVG 79 the SVG agreed that a single DCP should be raised to address all the issues that require changed to Code Subsidiary Documents.</p>	
<p><b>Justification for Change</b> <i>(mandatory by originator)</i></p> <p>The issues defined in the Solution Catalogue affect both the accuracy of the data entering Settlement and the efficiency of the BSC processes.</p> <p>‘Erroneous values of Unmetered Supplies (UMS) in the NHH Market’ was the biggest issue in the BSC Auditor’s Report for the year ended 31 March 2006, contributing 491,000 MWh (42%) of estimated uncorrectable error to the total of 1,164,000 MWh. The BSC Auditor’s Report for the year ended 31 March 2007 has now estimated that the uncorrectable error is now in the region of 287,000 MWh (34% of the total error for 2007).</p>	
<p><b>Proposed Solution(s)</b> <i>(mandatory by originator)</i></p> <p>The solutions proposed by this DCP are detailed in Attachment A. Part 1 of the Attachment details the proposals arising from the audit issues; in some instances a number of options were identified by the group and these require input from industry. Part 2 sets out a series of changes to BSCPs to correct the defects identified by the walkthrough.</p>	

<p align="center"><b>Draft Change Proposal – BSCP40/01</b></p>	<p>DCP No: 0029</p> <p><i>Version No: 1.0 (mandatory by BSCCo)</i></p>
<p><b>Version History (mandatory by BSCCo)</b></p> <p>N/A</p>	
<p><b>Has this DCP been raised for discussion by a Working Group (optional by originator):</b> No</p>	
<p><b>Originator's Details:</b></p> <p><i>BCA Name.....Steve Francis.....</i></p> <p><i>Organisation.....ELEXON.....</i></p> <p><i>Email Address.....steve.francis@elexon.co.uk.....</i></p> <p><i>Telephone Number.....020 7380 4038.....</i></p> <p><i>Date.....29 February 2008.....</i></p>	
<p>Attachments: Yes</p> <p>DCP0029 Attachment A (4 pages)</p>	