

Change Proposal – F40/01 (Page 1 of 2)

CP No: 830
(mandatory by BSCCo)

Title (mandatory by originator)

Service Description updates to reflect Code changes between v1.0 and v1.1 relating to Contingency Provisions and Supplier of Last Resort

Description of Change (mandatory by originator)

BSC Agent Service Descriptions need to be updated to reflect the changes made to between v1.0 and v1.1 of the Code that relate to Contingency Provisions. These include the following:

- Failing Supplier Process
- Suspension of Balancing Mechanism
- Manifest Errors
- Suspension of Contract Volume Notifications
- Black Start – Contingency
- Civil Emergencies and Fuel Security Periods
- Generator Compensation Instructions
- Single Imbalance Cashout Price

Detailed changes are contained in the attached redlined Service Descriptions.

Proposed Solution(s) (mandatory by originator)

Amend the following CSDs:

- BMRA Service Description
- CRA Service Description
- ECVAA Service Description
- FAA Service Description
- SAA Service Description

Justification for Change (mandatory by originator)

Amendments made to the Code between version 1.0 and 1.1 were not reflected in the BSC Agent Service Descriptions. These changes were implemented in the last week before Go-Live. Although NCR 282 was implemented to make the necessary changes to BSC systems, the subsidiary documents were not amended.

Amendments are now therefore required to BSC Agents' Service Descriptions to ensure the obligations in the Code relating Contingency Arrangements, are clearly recorded as contractual obligations on BSC Agents.

Change Proposal – F40/01 (Page 2 of 2)

CP No: 830
(mandatory by BSCCo)

Other Configurable Items Potentially Affected by Proposed Solution(s) *(optional by BSCCo)*

BSC Agent URSS and the IDD may be impacted, especially in relation to the ECVAA service.

Impact on Core Industry Documents *(optional by originator)*

Related Changes and/or Projects *(mandatory by BSCCo)*

CP739 – Service Description Updates to reflect Code changes v1.0 to v1.1 other than Contingency Provisions and SoLR: This CP covers ECVAA process that were altered in v1.1 of the Code but do not strictly form part of the Contingency Provisions as stated in Section G of the Code. The issues included in CP739 include ECVAA System Failure and Withdrawal, resubmission of ECVNs and MVRNs, and dealing with notifications relating to clock change days.

Originator's Details:

BCA Name... *Steve Francis*

Organisation.....*ELEXON.....*

Email Address.....*steve.francis@elexon.co.uk.....*

Date... *4 July 2002*

Organisation... ..

Attachments:

- BMRA Service Description
- CRA Service Description
- ECVAA Service Description
- FAA Service Description
- SAA Service Description