

## Attachment 4

Table of Impacts on Charges for Licence Exempt Generation and Associated Demand

Existing Options	Reduce Elexon Charges	Reduce TX Losses	Reduce RCRC Allocat'n	Submitting Bids/Offer	Informat'n Imbalance	Reduce TNUoS	Reduce BSUoS
Register in SVA as "negative demand"	Up to level of associated demand (Single BMU)	Up to level of associated demand (Single BMU)	Up to level of associated demand (Single BMU)	Risk of under delivery given demand volatility	Charged on Aggregate	Up to level of associated demand (Single BMU)	Up to level of associated demand (Single BMU)
Operate as Export Exempt Generator	No Impact	No Impact	No Impact	Only Generator Bid & Offer risk	No Impact	Up to level of associated demand (Multiple- BMU)	No Impact
Form TU with Export Exempt Generator and supply BMU	Up to level of associated demand (Single BMU)	Up to level of associated demand (Single BMU)	Up to level of associated demand (Single BMU)	Only Generator Bid & Offer risk	No Impact	Up to level of associated demand (Single BMU)	Up to level of associated demand (Single BMU)
Use SVA Meter Splitting (Divide output between two Supplier BMUs)	Up to level of associated demand (Two BMUs)	Up to level of associated demand (Two BMUs)	Up to level of associated demand (Two BMUs)	Risk of under delivery given demand volatility	Charged on Aggregate	Up to level of associated demand (Two BMUs)	Up to level of associated demand (Two BMUs)
Use "Change of Supplier" Process	This process could be used to create a larger supplier BMU that could be used in the above options. The process is however slow and cumbersome						
<b>Proposed Option</b>							
Allow any LEGs and supplier BMU's within GSP to form TU	Up to associated demand (Multiple BMUs)	Up to associated demand (Multiple BMUs)	Up to associated demand (Multiple BMUs)	Only Generator Bid & Offer risk	No Impact	Up to associated demand (Multiple BMUs)	Up to associated demand (Multiple BMUs)

## Summary table

<b>Existing Options</b>	<b>Comments</b>
Register in SVA as "negative demand"	Must have supplier BMU larger than LEG for full benefit. Can only use one supplier BMU.
Operate as Export Exempt Generator	Only avoids TNUoS charges (but can triad trade with several supply BMUs)
Form TU with Export Exempt Generator and supply BMU	Must have supplier BMU larger than LEG for full benefit. Can only use one supplier BMU.
Use "Change of Supplier Process"	Too slow and cumbersome
Use SVA Meter Splitting	Only allows use of 2 supplier BMUs and must specify how output will be split in advance
<b>Proposed Option</b>	
Allow any LEGs and supplier BMU's within GSP to form TU	Maximises Embedded Benefits