

Modification Proposal	MP No: P151 <i>(mandatory by BSCCo)</i>
Title of Modification Proposal <i>(mandatory by proposer):</i> Housekeeping Modification	
Submission Date <i>(mandatory by proposer):</i> 28 November 2003	
Description of Proposed Modification <i>(mandatory by proposer):</i> To rectify minor inconsistencies, typographical errors and omissions within the BSC.	
Description of Issue or Defect that Modification Proposal Seeks to Address <i>(mandatory by proposer):</i> See Appendix 1	
Impact on Code <i>(optional by proposer):</i> See Appendix 1	
Impact on Core Industry Documents <i>(optional by proposer):</i> None	
Impact on BSC Systems and Other Relevant Systems and Processes Used by Parties <i>(optional by proposer):</i> None	
Impact on other Configurable Items <i>(optional by proposer):</i> None	
Justification for Proposed Modification with Reference to Applicable BSC Objectives <i>(mandatory by proposer):</i> The BSC Panel can raise a Modification Proposal to address the minor inconsistencies, manifest errors or minor consequential changes in accordance with Section F2.1.1(d)(iv) of the Code. The Applicable Objective is in condition C(3)(d) of the Transmission Licence to promote efficiency in the implementation and administration of the balancing and settlement arrangements.	
Details of Proposer: Name: Organisation: BSC Panel Telephone Number: Email Address:	
Details of Proposer's Representative: Name: Modification Secretary Organisation: ELEXON Telephone Number: 0207 380 4100 Email Address: chris.rowell@elexon.co.uk	

Modification Proposal

MP No: P151
(mandatory by BSCCo)

Details of Representative's Alternate:

Name:

Organisation:

Telephone Number:

Email Address:

Attachments: YES

If Yes, Title and No. of Pages of Each Attachment:

Log of Proposals – 2 pages

Appendix 1 – Log of Proposals

	Identified by	Section(s)/ Area(s) Affected	Type of Change	Description of Change
1.	ELEXON	Section S 2.2	Omission.	Section 2.2.1 insert 'and BSCP 514' after 'in accordance with Party Service Line 110' and before 'for Meter Operation'.
2.	ELEXON	Section S 2.2	Typographical error.	Section 2.2.1 replace BSPC with BSCP.
3.	ELEXON	Section T, Annex T-2	Typographical error.	Annex T-2, para 1.3 (c) should refer to "slack node" instead of "slack mode" Annex T-2, para 5.2 should refer to "Network Data" instead of "Network Date"
4.	ELEXON	Section F 1.7.2(e)	Typographical error.	F1.7.2(e) says "Approval Modification" and it should say "Approved Modification".
5.	ELEXON	Section L 2.3.1	Minor inconsistency.	Section L2.3.1 states: (a) the Registrant shall ensure that Metering Equipment is installed and commissioned in accordance with paragraph 2.1.1(a) and that a proving test in accordance with BSCP 20 has been successfully completed before the registration of the Metering System becomes effective; With the implementation of CP821, the reference to BSCP 20 should be replaced by a reference to the new BSCP 02.
6.	ELEXON	Section P	Typographical error.	P 5.1.1 g Systemm - (should be System) P 5.3.2 c) ii System - (should be System)
7.	ELEXON	Section C 2.7.1	Typographical error.	Section C2.7.1 of section Cv5 - Subsidiaries (should be Subsidiaries)
8.	ELEXON	Section M 2.2.1(b)	Omission.	Section M (V7.0), 2.2.1(b) ... "and the amount of any new Letter of Credit plus cash so delivered shall not BE less than that of the current Letter of Credit;" (the 'be' is missing).
9.	ELEXON	Section T 4.6.5	Typographical error.	Section T (V10.0) 4.6.5 refers to TQASj - the 'j' should be subscripted.

10.	ELEXON	Section W 3.3.1 (a) & 3.6.1	Typographical error.	Typo in 3.3.1 (a) whereby 'and' included after semi-colon should be moved to end of 3.3.1 (b).
11.	ELEXON	Section F 2.4.14	Typographical error.	2.4.14 Linespace needs deleting
12.	ELEXON	Section L 1.2.1, 1.2.3, 1.2.4, 2.4.1 & 2.5.1	Omission.	Now that BSCP514 has been approved (Implementation Date 28 August 2003), a number of references should be added to it in the Code, to show that processes should be carried out in accordance with it (currently the code states that processes should be carried out in accordance with PSL110 in these cases). The additions are to Section L: Metering (Version 2 produced on 6 June 2003). Paragraphs 1.2.1, 1.2.3, 1.2.4, 2.4.1 and 2.5.1 all contain the text 'Party Service Line 110' Immediately after this text should be added 'and BSCP514'
13.	ELEXON	Section U 1.6.2	Minor inconsistency.	Changes required to P107 baseline to be consistent with P82. The TLFA should be added to the list of agents in U 1.6.2(a)
14.	ELEXON	Annex X-1	Typographical error.	The definition of BM Auditor in Annex X-1 should refer to Section H5.1.6 not H5.1.5.
15.	ELEXON	Section M3.4.3(a)	Typographical error.	Replace "principals" with "principles"
16.	ELEXON	Section T	Typographical error.	T 4.4.6A (c) has a red underline remaining between zero, and SBP. T4.4.10 needs to have a number of the 'j' subscripted (as they are normal font) - indicated in red below: $TCQ_j = \{ \{ (\sum_i \sum^{n'} QAPB_{ij}^{n'}) + TTQUAB_j + TESVA_j + TSSVA_j \} - \{ (\sum_i \sum^{n*} QAPO_{ij}^{n*}) + TTQUAO_j + TEBVA_j + TSBVA_j \} \} / 2$
17.	ELEXON	Section T 3.6	Minor inconsistency.	This section appears to use two different notations to refer to the Acceptance whose Acceptance time most recently precedes that of Acceptance k. This looks like an inconsistency, the k-1 should be referred to as k- throughout.