

Change Proposal – F40/01	<p>CP No: 938</p> <p><i>Version No:</i></p>
<p>Title <i>(mandatory by originator)</i> Incorrect footnote reference in BSCP504 3.3.10.2</p>	
<p>Description of Problem/Issue <i>(mandatory by originator)</i></p> <p>The last clause of section 3.3.10.2 (Changes to SVA Metering System Standing Data) of BSCP504 relates to change of Profile Class where no reading has been obtained, and states that:-</p> <p>"If no meter reading required, confirm the effective date of the Profile Class change".</p> <p>This is to be effected by a D0010 "Meter Readings" flow from the NHH Data Collector to the Supplier.</p> <p>There is a cross-reference in the "To" column to Footnote 34. This footnote states that "The Supplier may choose to raise a dispute, where in the Supplier's view, there is a difference of more than 250kWh from the original CoS reading". The footnote is (correctly) referenced by section 3.2.6.12 - "No later than 12 months after SDD, if the new Supplier wants to dispute the CoS reading prior to the Final Reconciliation Volume Allocation Run³⁴".</p>	
<p>Proposed Solution(s) <i>(mandatory by originator)</i></p> <p>Change existing reference to footnote 34 to footnote:- "The NHHDC will indicate there has been a change of Profile Class by sending a D0010 Meter Readings to the Supplier. In particular the following fields will be completed by the NHHDC : 'Additional Information' field - the NHHDC will confirm that the flow is a Profile Class change flow; if meter reading obtained, additionally the 'Reading Type' field will be completed - the NHHDC will select the 's' - for 'Special' value. This combination of data will enable the Supplier to identify that this is a change of Profile Class flow".</p> <p>This is footnote 67 in version 4.0 of BSCP504.</p>	

<p style="text-align: center;">Change Proposal – F40/01</p>	<p>CP No: 938</p> <p><i>Version No:</i></p>
<p>Justification for Change <i>(mandatory by originator)</i></p> <p>Raised as a Help Desk call (ref. PMR 29473) by SD Partners on behalf of IMServ NHH Data Collector. Issue is self-evident in version 4.0 of BSCP504.</p>	
<p>Configurable Items Potentially Affected by Proposed Solution(s) <i>(optional by Originator)</i></p>	
<p>Impact on Core Industry Documents <i>(optional by originator)</i></p>	
<p>Related Changes and/or Projects <i>(mandatory by BSSCo)</i></p>	
<p>Requested Implementation Date <i>(mandatory by originator)</i></p> <p>Next appropriate release.</p> <p>Reason:</p>	

<p>Change Proposal – F40/01</p>	<p>CP No: 938</p> <p>Version No:</p>
<p>Agreed Release/Implementation Date (<i>mandatory by BSCCo</i>)</p>	
<p><i>Originator's Details:</i></p> <p><i>BCA Name.....Jon Spence</i></p> <p><i>Organisation.....ELEXON.....</i></p> <p><i>Email Address.....jon.spence@elexon.co.uk.....</i></p> <p><i>Date.....17/03/03.....</i></p>	
<p>Attachments: N</p>	