

Change Proposal – F40/01 (Page 1 of 2)		CP No: 596 (mandatory by BSCCo)
Title (mandatory by originator) Correction to the SAA URS		
Description of Change (mandatory by originator) The SAA URS v.2.4 Section F013 contains a minor error. In point 3 paragraph 2 it states that BSCC Ltd sets the FPN flag, when in fact the flag is set by the Lead Party as detailed in the CRA URS and BSCP15. <i>This Change Proposal has been raised to address NCR365.</i>		
Proposed Solution(s) (mandatory by originator) The following changes should be made to SAA-F013, point 3, paragraph 2: “FPN Flags apply to BM Units, the Lead Party BSCC Ltd will identify BM Units for which the flag will be set to ‘N’, the default value will be ‘Y’. This flag will be used to indicate whether a Party is required to submit an accurate FPN for a particular BM Unit or not. The Lead Party BSCC Ltd will set these FPN flags through the CRA interfaces.”		
Justification for Change (mandatory by originator) To remove inconsistencies between the SAA URS v.2.4, CRA URS v.2.4 and BSCP15 v.2.		
Other Configurable Items Potentially Affected by Proposed Solution(s) (optional by BSCCo)		
Impact on Core Industry Documents (optional by originator)		
Related Changes and/or Projects (mandatory by BSCCo)		
Originator's Details: BCA Name ...Stephen Francis..... OrganisationELEXON..... Email Addresssteve.francis@elexon.co.uk..... Date31 st May 2001..... Organisation		
Attachments: Y/N* (If Yes, No. of Pages attached:.....) (delete as appropriate)		