

Boundary Point Metering and BM Unit Issues in Section K - ISG Recommendation

155/10

- Keith Campion – 020 7380 4011
- 14 May 2009




155/10: Section F Issue




- » ELEXON presented 3 issues to the ISG in April
- » The ISG agreed that the BSC:
 - may require more meters than are necessary in 2 separate circumstances;
 - BMU configurations for wind farms may not be suitable;
- » ELEXON and the ISG recommended that a Section F Issue be raised.

155/10: The Issues – CCGT Modules




155/10: The Issues – Power Park Modules



155/10: The Issues – BMU Equipment



Boundary Point



Power diverted
via another BMU

155/10: Way Forward



- » Section F Issue to:
 - Consider possible solutions and
 - Recommend appropriate change

155/10: Recommendations



- » **NOTE** that the issues that have been identified with Section K of the BSC;
- » **NOTE** that the ISG considered these issues and agreed that they warranted further discussion to establish whether a Modification to the BSC would be appropriate; and
- » **AGREE** that these three matters be referred to the Standing Modification Group, as a single Issue under Section F of the BSC