

| | |
|--|--|
| <p align="center">Change Proposal – F40/02 (Page 1 of 2)</p> | <p>CP No: 757 <i>(mandatory by BSCCo)</i></p> |
| | |
| <p>Title Missing Timescale in PSL110 Section 5.3.2</p> | |
| <p>Description of Change <i>(mandatory by originator)</i></p> <p>The Service Level for Serial 1 in Section 5.3.2 of PSL110, "SVA Meter Operation", currently states:</p> <ul style="list-style-type: none"> i) 95% rectified within 5 WD of notification; ii) 99% rectified within WD of notification. <p>There is no timescale defined in ii) above.</p> | |
| <p>Proposed Solution(s) <i>(mandatory by originator)</i></p> <p>Amend the Service Level to:</p> <ul style="list-style-type: none"> ii) 99% rectified within 15 WD of notification. | |
| <p>Justification for Change <i>(mandatory by originator)</i></p> <p>No timescale is specified in the Service Level. 15 WD is the timescale utilised in PARMs Monitoring.</p> | |
| <p>Other Configurable Items Potentially Affected by Proposed Solution(s) <i>(optional by BSCCo)</i></p> <p>None</p> | |
| <p>Impact on Core Industry Documents <i>(optional by originator)</i></p> <p>None</p> | |
| <p>Related Changes and/or Projects <i>(mandatory by BSCCo)</i></p> <p>None</p> | |

Change Proposal – F40/01 (Page 2 of 2)

CP No:
(mandatory by BSCCo)

Originator's Details:

BCA Name

Organisation

Email Address

Date 05/02/2002

Attachments: N* (If Yes, No. of Pages attached:.....)
(delete as appropriate)