

<b>Change Proposal – BSCP40/02</b>	CP No: 1318  <i>Version No: v1.0</i> <i>(mandatory by BSCCo)</i>
<b>Title</b> <i>(mandatory by originator)</i>  Minor Changes to BSCP601	
<b>Description of Problem/Issue</b> <i>(mandatory by originator)</i>  A number of minor errors exist in BSCP601 ‘Metering Protocol Approval and Compliance Testing’ which this CP is seeking to address.	
<b>Proposed Solution</b> <i>(mandatory by originator)</i>  We believe that BSCP601 should be changed to: <ul style="list-style-type: none"> <li>• update old terminology and standards;</li> <li>• add necessary disclaimers;</li> <li>• remove version numbers from the Code of Practice definitions;</li> <li>• correct minor typos and incorrect grammar;</li> <li>• clarify phrasing; and</li> <li>• add a copy write acknowledgement.</li> </ul> <p>Attachment A contains a table of all of the minor errors that we have identified which we believe should be changed at the next opportunity.</p> <p>Attachment B shows the redlined text changes.</p>	
<b>Justification for Change</b> <i>(mandatory by originator)</i>  A number of errors exist in BSCP601 which are of a minor nature. Making these changes will make the document clearer to the Compliance Testing Agent and Applicants who are looking to submit Metering Equipment for compliance testing.	
<b>To which section of the Code does the CP relate, and does the CP facilitate the current provisions of the Code?</b> <i>(mandatory by originator)</i>  Section L (Metering). This CP will facilitate the provisions of the Code by ensuring that the lower level BSC requirements are clear and up to date.	
<b>Estimated Implementation Costs</b> <i>(mandatory by BSCCo)</i>  The estimated implementation effort is 1.75 days, equating to approximately £295.	
<b>Configurable Items Affected by Proposed Solution(s)</b> <i>(mandatory by originator)</i>  BSCP601 ‘Metering Protocol Approval and Compliance Testing’	

**Impact on Core Industry Documents or System Operator-Transmission Owner Code** *(mandatory by originator)*

None Identified

**Related Changes and/or Projects** *(mandatory by BSCCo)*

N/A

**Requested Implementation Date** *(mandatory by originator)*

Next available Release – June 2010

**Reason:**

Clarifying BSCP601 as soon as possible should help applicants understand the Meter/Outstation functionality being tested for (the sources of the requirements are the Codes of Practice themselves) and the Compliance Testing Agent will have clearer instructions on the functionality to test for.

**Version History** *(mandatory by BSCCo)*

This is version 1.0 for impact assessment.

**Originator's Details:**

**BCA Name**.....*Mike Smith*.....

**Organisation**.....*ELEXON Ltd.*.....

**Email Address**.....*mike.smith@elexon.co.uk*.....

**Telephone Number**.....*020 7380 4033*.....

**Date**.....*21 October 2009*.....

Attachments: Y

CP1318 Attachment A – Table of suggested changes (10 Pages)

CP1318 Attachment B – BSCP601 redlining (19 Pages)