

Change Proposal – F40/01 (Page 1 of 2)	CP No: 739 <i>(mandatory by BSCCo)</i>
Title <i>(mandatory by originator)</i> Services Description Updates to reflect Code changes v1.0 to v1.1 other than Contingency Provisions and SoLR	
Description of Change <i>(mandatory by originator)</i> BSC Agent Service Descriptions need to be updated to reflect the changes between version 1.0 of the Code and the Go-Live designated version (1.1). The following areas should be included in the CDCA and ECVAA Service Descriptions: <ul style="list-style-type: none"> ▪ Notification Clock Changes; ▪ Resubmission of Energy Contract Volume and Metered Volume Reallocation Notifications; ▪ Failures of the ECVAA System; ▪ ECVAA System Withdrawal; and ▪ Default Line Loss Factors. 	
Proposed Solution(s) <i>(mandatory by originator)</i> Redlined versions of the CDCA and ECVAA Service Descriptions are attached.	
Justification for Change <i>(mandatory by originator)</i> Amendments made to the Code between version 1.0 and 1.1 have not been reflected in the BSC Agent Service Descriptions. Amendments are now required to BSC Agent's Service Descriptions to ensure that obligations in the Code are clearly recorded as contractual obligations on BSC Agents.	
Other Configurable Items Potentially Affected by Proposed Solution(s) <i>(optional by BSCCo)</i>	
Impact on Core Industry Documents <i>(optional by originator)</i>	
Related Changes and/or Projects <i>(mandatory by BSCCo)</i> Modification P1 CP548	
Originator's Details: BCA Name Organisation Email Address Date ...18 December 2001..... Organisation	
Attachments: Yes - 2 Redlined Service Descriptions attached as separate documents	